

■ Order by Part Number

Cap Assembly

- 104590 3.5gpf
- 104591 1.6gpf

Replacement Piston*

- 104563 3.5gpf
- 104564 1.6gpf

Sweat Kit (1" supply)

- 104588 3" length
- 104589 6" length

Replacement Brass Stop

- 104555 1" Angle Stop

Angle Stop Cap Replacement

- 104572

See catalog for alternative size and conversion nipples.

Vacuum Breaker Assembly

- 104570

Handle Assembly

- 104569

Angle Stop Repair Kit

- 104557

Flush Valve Tube

- 104585 24"x1½"
- 104560 22½"x1½" Offset

Tail Piece & Interior Cap Tool

- 104597

Wall Mount Assembly

- 104573

Flush Valve Body Nut

- 104571

Arm Assembly

- 104575

Bedpan Washer Seal Kit

- 104574

Spray Face

- 104577

Lower Discharge Tube

- 104600 8½"x1½" Offset

Top Spud Assembly

- 104581 1½"

* Use of a replacement piston with flow rate (gpf) not intended for existing fixture is not recommended.

• Not included with any bedpan washer kit.

1-1/2" Manual Exposed Style Closet Flush Valve Bedpan Washer		
MODEL	STYLE	FLOW RATE (gpf)
8310BPW35	Closet with Bedpan Washer	3.5
8310BPW16	Closet with Bedpan Washer	1.6
8310BPWR	Bedpan Washer Diverter Kit	N/A